



CASE STUDY: **Wix & Wrabness Pre-school**

REQUIREMENT: The existing discoloured timber ramp became slippery when wet, and moss build-up on the surface contributed to this. Therefore, the client required a metal slip-resistant alternative.

ADDITIONAL INFORMATION: Moss does not grow on our galvanised steel ramps as it may on wooden ones; this is because our self-draining mesh allows water to pass through, leaving no moisture for moss to thrive on.

The mesh is manufactured from galvanised steel; galvanising is a process that involves applying a protective zinc coating that prevents rust and kills moss.


Our in-house design team created detailed 3D and 2D drawings of the system, which were provided to the client with their quotation.

Application: Education

Location: Manningtree, Essex

System: Standard Ramp System

Service Package: Supply & Install



END RESULT: The wooden ramp was dismantled and replaced with a metal Rapid Ramp.
The installation only took a few hours to complete.

FEATURES INCLUDED:

- Mesh Platform -The self-draining mesh allows water to pass through rather than collect on the surface.
- Trombone Ends - Added to the ends of the Rapid Ramp to prevent clothes from catching.
- Telescopic Legs - Adjustable legs that accommodate different threshold heights.
- Continuous Handrail - Ensures users always have support to hold onto.
- Standard Colour Black - Ramps are powder-coated black for a durable finish that is tougher than conventional paint.

EXTRA FEATURES INCLUDED:

- Infill Handrail - Prevents users from climbing or falling through gaps.
- Step Unit - An ideal addition to any ramp installation, providing access for able-bodied users. They can also function as stand-alone units, independent of the Rapid Ramp System.



I just wanted to say thank you for the speedy installation of our ramp. It is perfect and looks great. A big thank you to the guys for leaving absolutely no mess!

Pre-school Manager



TEL: **01424 714646**
EMAIL: **SALES@RAPIDRAMP.CO.UK**

Hours:
Open 8am - 5pm, Monday to Friday

Address:
10 Menzies Road, Ponswood Industrial Estate, St Leonards on Sea, East Sussex TN38 9BB

Does your wooden ramp need to be replaced?

Contact our sales team